





LEGEND

MW-1  Monitoring well location and number


B-2  Soil boring location and number

CMW-4  Clearwater monitoring well location and number


 Approximate excavation limits for 421 Santa Rosa Avenue site

Data for 421 Santa Rosa Avenue from Clearwater Group report dated September 20, 2005

Reference:
Ray Carlson & Associates, June 4, 2004



Brunsing Associates, Inc.
5468 Skylane Blvd., Suite 201
Santa Rosa, California 95403
Tel: (707) 838-3027

Job No.: 691
Appr: 
Date: 12/15/05

SITE MAP
505 Santa Rosa Avenue
Santa Rosa, California

PLATE
2